

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 10/23/2012	<b>Time:</b> 3:23 PM
<b>Name of School Corporation:</b> NORTH GIBSON SCHOOL CORP.	<b>Corp ID:</b> 262735	
<b>Address of School Corporation:</b> 1108 N Embree St		
<b>City:</b> Princeton	<b>Zip:</b> 47670	<b>County Number:</b> 26
<b>VIN:</b> 4DRBWAAR95A983509	<b>License Number:</b> 20791	<b>Bus Number:</b> 56
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2005	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2005	<b>Mileage:</b> Unknown	<b>Year:</b> 2005
<b>Bus Type:</b> D		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Chuck Tharp	<b>PE:</b> 5618

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
93-1-4	Any front turn signal does not function properly
93-1-2	A lens is cracked, missing or wrong color
62-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative.
10-1-4	Battery terminals are excessively corroded.
30-1-8	If required, positive door opening device is missing or fails to operate properly.
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
18-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
38-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**