

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks	Date: 10/24/2012	Time: 8:45 AM	
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625		
Address of School Corporation: PO Box 550			
City: Converse	Zip: 46919	County Number: 52	
VIN: 4DRBUSKN29B095305	License Number: 30876	Bus Number: 7	
Make of Body: IC Corporation	Year: 2009	Make of Chassis: IC Corporation	Year: 2009
Bus Type: C	Mileage: Unknown		
Inspection Status: O	Inspected By: Randy McPike	PE: 7018	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.