REPORT OF SCHOOL BUS INSPECTION

9:26 Type of Semi-Annual Date: 10/24/2012 **Time**: Inspection: AM Name of School Corporation: SHELBY EASTERN SCHOOLS 737285 Corp ID: **Address of School Corporation:** 2451 N 600 E County City: Shelbyville Zip: 46176 73 Number: License VIN: 1BABKCPH7YF090931 B715F **Bus Number:** 6 Number: Make of Blue Bird Year: 2000 Make of Body: AmTran Year: 1999 Corporation Chassis: **Bus Type:** Mileage: Unknown

Amy Gaul

PE:

5934

Inspected

By:

Inspection Status: O

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

34-1-1 There is significant engine oil or fluid leak from the engine.

34-1-4 There is a significant fluid leak from the transmission.

Violations - Out of Service

Inspection Code Description

46-2-1 There is a fuel leak from any line, connection or fitting.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.