

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Spot Checks	<b>Date:</b> 11/5/2012	<b>Time:</b> 1:05 PM
<b>Name of School Corporation:</b> NORTH GIBSON SCHOOL CORP.	<b>Corp ID:</b> 262735	
<b>Address of School Corporation:</b> 1108 N Embree St		
<b>City:</b> Princeton <b>Zip:</b> 47670	<b>County Number:</b> 26	
<b>VIN:</b> 4UZAAXCS96CV28453 <b>License Number:</b> B277D	<b>Bus Number:</b> 25	
<b>Make of Body:</b> Freightliner <b>Year:</b> 2006 <b>Make of Chassis:</b> Thomas Built Buses, Inc. <b>Year:</b> 2006		
<b>Bus Type:</b> C <b>Mileage:</b> Unknown		
<b>Inspection Status:</b> R <b>Inspected By:</b> Chuck Tharp	<b>PE:</b> 5618	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function
36-1-6	Tailpipe does not extend to, or extends beyond the perimeter of the bus body.
99-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**