

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Spot Checks	<b>Date:</b>	11/5/2012	<b>Time:</b>	1:11 PM
<b>Name of School Corporation:</b>	NORTH GIBSON SCHOOL CORP.			<b>Corp ID:</b>	262735
<b>Address of School Corporation:</b>	1108 N Embree St				
<b>City:</b>	Princeton	<b>Zip:</b>	47670	<b>County Number:</b>	26
<b>VIN:</b>	4UZABRDJ58CZ10917	<b>License Number:</b>	B167E	<b>Bus Number:</b>	2
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown	<b>Year:</b>	2008
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Chuck Tharp	<b>PE:</b>	5618

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-1	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49.
21-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative.
83-1-5	Step-well light is missing or inoperative
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.
59-1-4	There is debris in the bus. (needs cleaned) includes dirt

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.