REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 11/19/2012 Time: 8:04 PM Name of School Corporation: HONEY GROVE EDUCATIONAL DAYCARE Corp ID: 41001Z

Address of School Corporation: 1709 S SR 135

City:GreenwoodZip:46143County Number: 41VIN:1GBHG31RXX1146766License Number: B958ABBus Number: 2Make of Body:Chevrolet Year: 1999Make of Chassis: Chevrolet Year: 1999

Bus Type: Mileage: Unknown

Inspection Status: R Inspected By: Chris Kath PE: 6690

Violations - Rejected

Inspection Code	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function
30-1-7	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted).
34-1-1	There is significant engine oil or fluid leak from the engine.

Violations - Out of Service

Inspection Code Description

Bus Type Description