REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	11/19/2012	**Time:**	8:04 PM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31RXX1146766	**License Number:**	B958AB	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1999	**Make of Chassis:**	Chevrolet	**Year:**	1999
Bus Type:		**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Chris Kath	**PE:**	6690

Violations - Rejected

Inspection Code	Description
90-1-2	One (1) taillight or one (1) brake light does not function
36-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted).
34-1-1	There is significant engine oil or fluid leak from the engine.

Violations - Out of Service

Inspection Code	Description

Bus Type Description