

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 11/19/2012      **Time:** 8:04 PM  
**Name of School Corporation:** HONEY GROVE EDUCATIONAL DAYCARE      **Corp ID:** 41001Z  
**Address of School Corporation:** 1709 S SR 135  
**City:** Greenwood      **Zip:** 46143      **County Number:** 41  
**VIN:** 1GBHG31RXX1146766      **License Number:** B958AB      **Bus Number:** 2  
**Make of Body:** Chevrolet      **Year:** 1999      **Make of Chassis:** Chevrolet      **Year:** 1999  
**Bus Type:**      **Mileage:** Unknown  
**Inspection Status:** R      **Inspected By:** Chris Kath      **PE:** 6690

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function
36-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted).
34-1-1	There is significant engine oil or fluid leak from the engine.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------