

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	11/26/2012	<b>Time:</b>	11:39 AM
<b>Name of School Corporation:</b>	EVANSVILLE-VANDERBURGH SCH COR	<b>Corp ID:</b>	827995		
<b>Address of School Corporation:</b>	951 Walnut St				
<b>City:</b>	Evansville	<b>Zip:</b>	47713	<b>County Number:</b>	82
<b>VIN:</b>	4UZABRDU7BCAT7854	<b>License Number:</b>	33053	<b>Bus Number:</b>	209
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2011	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Kelly Hammond	<b>PE:</b>	6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
54-1-1	The latch does not secure the hood tightly.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
38-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**