

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/12/2012	Time:	9:03 AM
Name of School Corporation:	FRANKFORT COMMUNITY SCHOOLS	Corp ID:	121170		
Address of School Corporation:	50 S Maish Rd				
City:	Frankfort	Zip:	46041	County Number:	12
VIN:	4DRBWAAR68A495090	License Number:	20596	Bus Number:	17
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Year:	2008	Year:	2008		
Bus Type:	D	Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Joel Flores	PE:	7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.