REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	1/8/2013	**Time:**	8:33 AM
Name of School Corporation:	GREENSBURG COMMUNITY SCHOOLS			**Corp ID:**	161730
Address of School Corporation:	1312 W Westridge Parkway				
City:	Greensburg	**Zip:**	47240	**County Number:**	16
VIN:	4DRBRAAP54B960632	**License Number:**	B4466G	**Bus Number:**	10
Make of Body:	IC Corporation **Year:** 2004	**Make of Chassis:**	IC Corporation	**Year:**	2004
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Chris Clark	**PE:**	6665

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
52-2-2	Two (2) leaf springs (other than the top two (2) leaves) are broken
9-2-1	The master cylinder is leaking at any point.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.