REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	1/15/2013	**Time:**	9:55 AM
Name of School Corporation:	DECATUR COUNTY COMM. SCHOOL			**Corp ID:**	161655
Address of School Corporation:	1645 W SR 46				
City:	Greensburg **Zip:**	47240		**County Number:**	16
VIN:	4UZABRDD48CZ10899	**License Number:**	31564	**Bus Number:**	5
Make of Body:	Freightliner **Year:** 2008	**Make of Chassis:**	Freightliner	**Year:**	2008
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	R **Inspected By:**	Chris Clark		**PE:**	6665

Violations - Rejected

Inspection Code	Description
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.