

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 2/6/2013	<b>Time:</b> 9:40 AM
<b>Name of School Corporation:</b> M.S.D. LAWRENCE TOWNSHIP		<b>Corp ID:</b> 495330
<b>Address of School Corporation:</b> 5850 Thunderbird Rd		
<b>City:</b> Indianapolis	<b>Zip:</b> 46236	<b>County Number:</b> 49
<b>VIN:</b> 4DRBWAAR4AA182383	<b>License Number:</b> 30340	<b>Bus Number:</b> 136
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2010	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2010		<b>Year:</b> 2010
<b>Bus Type:</b> D	<b>Mileage:</b> Unknown	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Amy Gaul	<b>PE:</b> 5934

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**