

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	2/7/2013	<b>Time:</b>	9:14 AM
<b>Name of School Corporation:</b>	NORTH VERMILLION COMM SCH CORP			<b>Corp ID:</b>	838010
<b>Address of School Corporation:</b>	5551 N Falcon Dr				
<b>City:</b>	Cayuga	<b>Zip:</b>	47928	<b>County Number:</b>	83
<b>VIN:</b>	1HVBRAAN61A937312	<b>License Number:</b>	B916F	<b>Bus Number:</b>	10
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2001	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>	2001	<b>Mileage:</b>	Unknown	<b>PE:</b>	5618
<b>Bus Type:</b>	C	<b>Inspected By:</b>	Chuck Tharp		
<b>Inspection Status:</b>	O				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
58-2-3	Stop arm does not fully extend to a right angle to the bus

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.