REPORT OF SCHOOL BUS INSPECTION

Type of 9:44 Annual 2/18/2013 **Time**: Date: Inspection: AM Name of School Corporation: MONROE COUNTY COMM. SCH. CORP. 535740 Corp ID: **Address of School Corporation:** 505 E North Dr County City: Bloomington Zip: 47401 53 Number: License VIN: 1GBJG31K791173267 83248 **Bus Number:** 121 Number: Thomas Built Buses, Make of Chevrolet Year: Make of Body: Year: 2011 2009 Inc. Chassis: **Bus Type:** Mileage: Unknown Inspected Inspection Status: O PE: Mark Raper 6473 By:

Violations - Rejected

Inspection Code Description

An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description