REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	2/20/2013	**Time:**	9:28 AM
Name of School Corporation:	EAST ALLEN COUNTY SCHOOLS				**Corp ID:**	20255
Address of School Corporation:	1322 Green Rd					
City:	New Haven	**Zip:**	46774		**County Number:**	2
VIN:	4DRBVAAN76A295509		**License Number:**	21294	**Bus Number:**	12
Make of Body:	IC Corporation	**Year:** 2006	**Make of Chassis:**	IC Corporation	**Year:**	2006
Bus Type:	D		**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Eric Egbert		**PE:**	7006

Violations - Rejected

Inspection Code	Description
21-1-1	A dripping oil or fluid leak.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.