

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 2/15/2013	<b>Time:</b> 9:40 AM
<b>Name of School Corporation:</b> SOUTHWESTERN JEFFERSON CO SCH CORP	<b>Corp ID:</b> 394000	
<b>Address of School Corporation:</b> 239 Main St		
<b>City:</b> Hanover	<b>Zip:</b> 47243	<b>County Number:</b> 39
<b>VIN:</b> 1GBHG31F511211620	<b>License Number:</b> 59621	<b>Bus Number:</b> R2
<b>Make of Body:</b> Chevrolet	<b>Year:</b> 2001	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2001	<b>Mileage:</b> Unknown	
<b>Bus Type:</b> B		
<b>Inspection Status:</b> A	<b>Inspected By:</b> Troy Boyd	<b>PE:</b> 5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**