REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | Date: | 2/25/2013 | Time: | 10:53 AM |
|---------------------|---------------|---------------|------------------|-----------|-----------------------|----------|
| Name of School Cor | CHOOLS | | Corp ID: | 454700 | | |
| Address of School C | orporation: | 602 N Raymon | d | | | |
| City: | Griffith | Zip: | 46319 | | County Number: | 45 |
| VIN: | 1GDHG31F82 | 1229392 | License Number: | 64762 | Bus Number: | 22 |
| Make of Body: | Corbeil Year: | 2003 | Make of Chassis: | GMC | Year: | 2003 |
| Bus Type: | | | Mileage: | Unknown | | |
| Inspection Status: | R | Inspected By: | Nathan Sherer | | PE: | 7029 |

Violations - Rejected

| Inspection Code | Description |
|-----------------|----------------------------------------------------------------------|
| 110-1-1 | The lifting mechanism is unable to lift a minimum load of 800 pounds |
| 16-1-1 | Dome light is inoperative. |

Violations - Out of Service

Inspection Code Description

Bus Type Description