

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 2/27/2013 **Time:** 1:49 PM
Name of School Corporation: EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725
Address of School Corporation: 941 S Franklin St
City: Oakland City **Zip:** 47660 **County Number:** 26
VIN: 1GB6G3AG8A1145550 **License Number:** 2370 **Bus Number:** 21
Make of Body: Star Trans **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: **Mileage:** Unknown
Inspection Status: R **Inspected By:** Chuck Tharp **PE:** 5618

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
19-1-8	If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description