REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	2/27/2013 **Time:**	1:49 PM
Name of School Corporation:	EAST GIBSON SCHOOL CORPORATION			**Corp ID:**	262725
Address of School Corporation:	941 S Franklin St				
City:	Oakland City	**Zip:**	47660	**County Number:**	26
VIN:	1GB6G3AG8A1145550		**License Number:**	2370 **Bus Number:**	21
Make of Body:	Star Trans **Year:**	2010	**Make of Chassis:**	Chevrolet **Year:**	2010
Bus Type:			**Mileage:**	Unknown	
Inspection Status:	R	**Inspected By:**	Chuck Tharp	**PE:**	5618

Violations - Rejected

Inspection Code	Description
19-1-8	If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

Inspection Code	Description

Bus Type Description