## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/27/2013 Time:1:25 PM

Name of School Corporation: EAST GIBSON SCHOOL CORPORATION Corp ID: 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1165037License Number:2369Bus Number:22Make of Body:Star Trans Year:2010Make of Chassis:ChevroletYear:2010

Bus Type: Mileage: Unknown

Inspection Status: R Inspected By: Chuck Tharp PE: 5618

**Violations - Rejected** 

<u>Inspection Code</u> <u>Description</u>

One (1) taillight or one (1) brake light does not function

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**