

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/15/2013 **Time:** 11:50 AM
Name of School Corporation: M.S.D. WARREN TWP. **Corp ID:** 495360
Address of School Corporation: 9150 Rawles
City: Indianapolis **Zip:** 46229 **County Number:** 49
VIN: 4DRBWAAR58A501977 **License Number:** 30794 **Bus Number:** 52
Make of Body: IC Corporation **Year:** 2008 **Make of Chassis:** IC Corporation **Year:** 2008
Bus Type: D **Mileage:** Unknown
Inspection Status: O **Inspected By:** John Pang **PE:** 6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle
61-1-2	One (1) taillight or one (1) brake light does not function
27-1-2	The first aid kit is not properly filled.
21-1-1	A dripping oil or fluid leak.
34-1-1	Heater motor is not operating properly.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-2	Body surface protrudes beyond the normal limits of the body structure.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
14-2-1	Defroster system is inoperative.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.