

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 3/15/2013 **Time:** 9:31 AM
Name of School Corporation: BLUE RIVER SERVICES **Corp ID:** 450001
Address of School Corporation: 3141 Progress Blvd.
City: Corydon **Zip:** 47112 **County Number:** 31
VIN: 1GBJG31U351244007 **License Number:** 68708 **Bus Number:** 93
Make of Body: Chevrolet **Year:** 2006 **Make of Chassis:** Chevrolet **Year:** 2006
Bus Type: A2 **Mileage:** Unknown
Inspection Status: R **Inspected By:** Troy Boyd **PE:** 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
2-1-1	Required back-up lights do not function.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.