REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	3/19/2013	Time:	12:03 PM
Name of School Co	orporation:	HANC	OVER COMM. S	SCHOOL CORP.		Corp ID:	454580
Address of School	Corporation:		PO Box 645				
City:	Cedar Lake		Zip:	46303		County Number:	45
VIN:	4drbuskn3cb4	46696		License Number:	627	Bus Number:	4
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2012
Bus Type:	С			Mileage:	Unknown		
Inspection Status:	R		Inspected By:	Nathan Sherer		PE:	7029

Violations - Rejected

<u>Inspection</u> <u>Code</u>	Description
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.