REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	3/19/2013	Time:	11:57 AM
Name of School Co	orporation: HAN	OVER COMM. S	SCHOOL CORP.		Corp ID:	454580
Address of School	Corporation:	PO Box 645				
City:	Cedar Lake	Zip:	46303		County Number:	45
VIN:	4DRBUSKN5BB289	249	License Number:	74275	Bus Number:	28
Make of Body:	IC Corporation Year	2011	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	С		Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Nathan Sherer		PE:	7029

Violations - Rejected

Inspection Code	Description
27-1-2	The first aid kit is not properly filled.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.