

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/19/2013	<b>Time:</b> 11:13 AM	
<b>Name of School Corporation:</b> HANOVER COMM. SCHOOL CORP.	<b>Corp ID:</b> 454580		
<b>Address of School Corporation:</b> 14525 Wicker			
<b>City:</b> Cedar Lake	<b>Zip:</b> 46303	<b>County Number:</b> 45	
<b>VIN:</b> 1HVBBABN84H581279	<b>License Number:</b> 4706	<b>Bus Number:</b> 11	
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2004	<b>Make of Chassis:</b> Blue Bird Corporation	<b>Year:</b> 2004
<b>Bus Type:</b> C	<b>Mileage:</b> Unknown		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Nathan Sherer	<b>PE:</b> 7029	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**