

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/19/2013	Time:	10:10 AM
Name of School Corporation:	HANOVER COMM. SCHOOL CORP.			Corp ID:	454580
Address of School Corporation:	PO Box 645				
City:	Cedar Lake	Zip:	46303	County Number:	45
VIN:	4drbuskn8cb446693	License Number:	638	Bus Number:	1
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	Unknown	Year:	2012
Inspection Status:	R	Inspected By:	Nathan Sherer	PE:	7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
56-1-5	Step-well light is missing or inoperative
69-1-7	Emergency window is too difficult to open
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle
27-1-2	The first aid kit is not properly filled.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.