REPORT OF SCHOOL BUS INSPECTION

12:57

Type of 3/21/2013 Time: Annual Date: Inspection: PM Name of School Corporation: PERU COMMUNITY SCHOOLS 525635 Corp ID: **Address of School Corporation:** 35 W 3rd St County City: Peru Zip: 46970 52 Number: License VIN: 4UZAAXCS07CW10993 21249 **Bus Number:** Number:

Make of Thomas Built Buses, Year: 2007 Freightliner Year: Make of Body: 2007 Inc. Chassis:

Bus Type: C Mileage: Unknown

Inspection Inspected R PE: 7018 Randy McPike Status: By:

Violations - Rejected

Inspection Code Description

27-1-2 The first aid kit is not properly filled.

Clearance light is missing, cracked, faded, wrong color, or inoperative. 12-1-1

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.