

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Registration	Date: 3/22/2013	Time: 9:15 AM	
Name of School Corporation: LAKE CENTRAL SCHOOL CORP.	Corp ID: 454615		
Address of School Corporation: 8855 Wicker Ave			
City: St John	Zip: 46373	County Number: 45	
VIN: 4DRBUSKN7EB418354	License Number: 731525	Bus Number: 44	
Make of Body: IC Corporation	Year: 2014	Make of Chassis: IC Corporation	Year: 2014
Bus Type: C	Mileage: Unknown		
Inspection Status: R	Inspected By: Nathan Sherer	PE: 7029	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.
56-1-5	Step-well light is missing or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.