

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/2/2013 **Time:** 11:56 AM
Name of School Corporation: PRIMROSE SCHOOL OF W. FISHERS **Corp ID:** 290004
Address of School Corporation: 12609 Parkside Dr.
City: Fishers **Zip:** 46038 **County Number:** 29
VIN: 1GBHG31C081109884 **License Number:** B733D **Bus Number:** 1
Make of Body: Chevrolet **Year:** 2008 **Make of Chassis:** Chevrolet **Year:** 2008
Bus Type: A1 **Mileage:** Unknown
Inspection Status: O **Inspected By:** Amy Gaul **PE:** 5934

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-3	Any front tire has less than 4/32 inch tread depth when measured in a major groove.
62-1-4	Rear tire has less than 2/32 inch tread depth when measured in a major groove.
19-1-8	If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.