REPORT OF SCHOOL BUS INSPECTION

Type of 9:12 Time: Annual Date: 4/3/2013 Inspection: AM Name of School Corporation: CROWN POINT COMM. SCHOOL CORP. Corp ID: 454660 **Address of School Corporation:** 1151 E Summit County City: Crown Point Zip: 46307 45 Number: License VIN: 4UZAAXCS85CM97128 19928 **Bus Number:** 43 Number: Make of Thomas Built Buses, Year: 2004 Freightliner Year: Make of Body: 2004 Inc. Chassis:

Bus Type: C

Inspection Status: O Inspected By: David Eggers PE: 5191

Mileage:

Unknown

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.