

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 4/4/2013      **Time:** 9:02 AM  
**Name of School Corporation:** CREATIVE CAMPUS CHILD CARE      **Corp ID:** 290020  
**Address of School Corporation:** 19043 Cumberland Rd.  
**City:** Noblesville      **Zip:** 46060      **County Number:** 29  
**VIN:** 1GBHG31V961133180      **License Number:** B117F      **Bus Number:** 1  
**Make of Body:** Chevrolet      **Year:** 2006      **Make of Chassis:** Chevrolet      **Year:** 2006  
**Bus Type:** A1      **Mileage:** Unknown  
**Inspection Status:** R      **Inspected By:** Amy Gaul      **PE:** 5934

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
21-1-1	A dripping oil or fluid leak.
67-1-1	Washers do not function properly in any manner
68-1-2	Wiper blades fail to contact the windshield properly
82-1-1	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**