## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:4/8/2013Time:9:49 AMName of School Corporation:CARROLL CONS. SCHOOL CORP.Corp ID:80750

Address of School Corporation: 2 S 3rd St.

City: Flora Zip: 46929 County Number: 8
VIN: 4DRBUAAP36B231031 License Number: 21036 Bus Number: 8
Make of Body: IC Corporation Year: 2006 Make of Chassis: IC Corporation Year: 2006

Bus Type: C Mileage: Unknown

Inspection Status: R Inspected By: Nate King PE: 7421

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

45-1-5 Upholstery or padding is ripped, torn, or improperly repaired.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.