

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/12/2013 **Time:** 9:47 AM
Name of School Corporation: 21ST CENTURY CHARTER AT GARY **Corp ID:** 130004
Address of School Corporation: 1440 E 35TH
City: Gary **Zip:** 46409 **County Number:** 45
VIN: 1GBJG31U541134848 **License Number:** B202G **Bus Number:** 1
Make of Body: Collins Bus Corporation **Year:** 2004 **Make of Chassis:** Chevrolet **Year:** 2004
Bus Type: A2 **Mileage:** Unknown
Inspection Status: O **Inspected By:** David Eggers **PE:** 5191

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
42-1-1	Lettering, numbers and/or placard do not conform to required size, color or location.
34-1-1	Heater motor is not operating properly.
40-1-4	There is debris in the bus. (needs cleaned) includes dirt
59-1-1	Sun visor is missing, cracked or broken

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
49-2-1	There is no seat belt cutter in the vehicle.
8-2-1	There is no brake certification, the certification has expired, or is not signed within the six month requirement.
61-2-1	Two (2) or more taillights or brake lights do not function

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**