REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	4/17/2013	**Time:**	8:55 AM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.			**Corp ID:**	485280
Address of School Corporation:	1306 N Anderson St				
City:	Elwood	**Zip:**	46036	**County Number:**	48
VIN:	1GDHG31F3X1065346	**License Number:**	25960	**Bus Number:**	A1
Make of Body:	Corbeil **Year:** 1999	**Make of Chassis:**	GMC	**Year:**	1999
Bus Type:		**Mileage:**	Unknown		
Inspection Status:	A	**Inspected By:**	Dave Whitinger	**PE:**	6480

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description

Bus Type	Description