REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	4/17/2013	Time:	8:55 AM
Name of School Cor	poration: ELW	OOD COMMUN	ITY SCHOOL COR	P.	Corp ID:	485280
Address of School C	orporation:	1306 N Anders	son St			
City:	Elwood	Zip:	46036		County Number:	48
VIN:	1GDHG31F3>	(1065346	License Number:	25960	Bus Number:	A1
Make of Body:	Corbeil Year	: 1999	Make of Chassis:	GMC	Year:	1999
Bus Type:			Mileage:	Unknown		
Inspection Status:	А	Inspected By:	Dave Whitinger		PE:	6480

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description