REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 4/17/2013 | Time: | 8:38 AM |
|---------------------------------|----------------------------|----------------------------|--------------------|---------------------|-----------|-------------------|------------|
| Name of School Corporation: ELW | | OOD COMMUNITY SCHOOL CORP. | | | Corp ID: | 485280 | |
| Address of School Corporation: | | | 1306 N Anderson St | | | | |
| City: | Elwood | | Zip: | 46036 | | County Number: | 48 |
| VIN: | 1GB6G2AG3A114742 | 6 | | License Number: | 83583 | Bus Number: | A3 |
| Make of Body: | Collins Bus Corporation | Year: | : 2010 | Make of Chassis: | Chevrolet | Year: | 2010 |
| Bus Type: | | | | Mileage: | Unknown | | |
| Inspection Status | : A | | Inspected By: | Dave Whitinger | | PE: | 6480 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description