REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:** 4/17/2013	**Time:**	8:28 AM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.			**Corp ID:**	485280
Address of School Corporation:	1306 N Anderson St				
City:	Elwood	**Zip:**	46036	**County Number:**	48
VIN:	1GB62AG0A11397198		**License Number:** 835821	**Bus Number:**	A2
Make of Body:	Collins Bus Corporation	**Year:** 2010	**Make of Chassis:** Chevrolet	**Year:**	2010
Bus Type:			**Mileage:** Unknown		
Inspection Status:	A	**Inspected By:**	Dave Whitinger	**PE:**	6480

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description

Bus Type	Description