

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/22/2013	<b>Time:</b> 10:57 AM
<b>Name of School Corporation:</b> LAPORTE COMMUNITY SCHOOL CORP.	<b>Corp ID:</b> 464945	
<b>Address of School Corporation:</b> 200 Stevens		
<b>City:</b> La Porte	<b>Zip:</b> 46350	<b>County Number:</b> 46
<b>VIN:</b> 1BAKF CPA09F260314	<b>License Number:</b> 31801	<b>Bus Number:</b> 47
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2009	<b>Mileage:</b> Unknown	<b>Year:</b> 2009
<b>Bus Type:</b> C		
<b>Inspection Status:</b> R	<b>Inspected By:</b> David Eggers	<b>PE:</b> 5191

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.
56-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.