REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	4/22/2013	Time:	9:43 AM
Name of School Corporation:		LAPORTE COMMUNITY SCHOOL CORP.			Corp ID:	464945
Address of School	Corporation:	1921 A St				
City:	La Porte	Zip:	46350		County Number:	46
VIN:	4DRBUSKN8CB088	544	License Number:	2729	Bus Number:	30
Make of Body:	IC Corporation Year	: 2011	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	С		Mileage:	Unknown		
Inspection Status:	0	Inspected By:	David Eggers		PE:	5191

Violations - Rejected

Inspection Code	Description
16-1-1	Dome light is inoperative.
56-1-5	Step-well light is missing or inoperative
27-1-2	The first aid kit is not properly filled.

Violations - Out of Service

Inspection CodeDescription7-2-4Any brake line or hose is abraded (chafed), cracked, bulging or leaking.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.