REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/22/2013 Time: 9:43 AM Name of School Corporation: LAPORTE COMMUNITY SCHOOL CORP. Corp ID: 464945

Address of School Corporation: 1921 A St

City:La PorteZip:46350County Number: 46VIN:4DRBUSKN8CB088544License Number: 2729Bus Number: 30Make of Body:IC Corporation Year: 2011Make of Chassis: IC Corporation Year: 2011

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: David Eggers PE: 5191

Violations - Rejected

Inspection CodeDescription16-1-1Dome light is inoperative.56-1-5Step-well light is missing or inoperative27-1-2The first aid kit is not properly filled.

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.