## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	4/23/2013	Time:	10:27 AM
Name of School Co	orporation:	LAPORTE COMMUN	NITY SCHOOL COP	RP.	Corp ID:	464945
Address of School	Corporation:	1921 A St				
City:	La Porte	Zip:	46350		County Number:	46
VIN:	4DRBWAAR3	CB378540	License Number:	: 151	Bus Number:	82
Make of Body:	IC Corporation	Year: 2012	Make of Chassis:	: IC Corporation	Year:	2010
Bus Type:	D		Mileage:	Unknown		
Inspection Status:	R	Inspected By:	David Eggers		PE:	5191

## **Violations - Rejected**

Inspection Code	<b>Description</b>
56-1-5	Step-well light is missing or inoperative
27-1-2	The first aid kit is not properly filled.

**Violations - Out of Service** 

Inspection Code Description

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.