

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	4/29/2013	<b>Time:</b>	10:54 AM		
<b>Name of School Corporation:</b>	OAK HILL UNITED SCHOOL CORP.			<b>Corp ID:</b>	525625		
<b>Address of School Corporation:</b>	PO Box 550						
<b>City:</b>	Converse	<b>Zip:</b>	46919	<b>County Number:</b>	52		
<b>VIN:</b>	4UZAAXBV72CJ95823	<b>License Number:</b>	1124	<b>Bus Number:</b>	6		
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2002	<b>Make of Chassis:</b>	Freightliner	<b>Year:</b>	2002
<b>Bus Type:</b>	B	<b>Mileage:</b>	Unknown				
<b>Inspection Status:</b>	A	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018		

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**