

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/29/2013	Time: 8:40 AM	
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625		
Address of School Corporation: PO Box 550			
City: Converse	Zip: 46919	County Number: 52	
VIN: 1HVBBAAN32H530898	License Number: 1119	Bus Number: 11	
Make of Body: Blue Bird Corporation	Year: 2003	Make of Chassis: IC Corporation	Year: 2003
Bus Type: C	Mileage: Unknown		
Inspection Status: R	Inspected By: Randy McPike	PE: 7018	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-8	Required reflective tape is applied in the wrong location, missing, and wrong width or badly faded

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.