

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/17/2013	Time:	9:29 AM
Name of School Corporation:	MEDORA COMMUNITY SCHOOL CORP.			Corp ID:	363640
Address of School Corporation:	Box 248				
City:	Medora	Zip:	47260	County Number:	36
VIN:	1BAKFCPA4BF274979	License Number:			4413 Bus Number: 2
Make of Body:	Blue Bird Corporation	Year:	2010	Make of Chassis:	Blue Bird Corporation Year: 2010
Bus Type:	C	Mileage:			Unknown
Inspection Status:	O	Inspected By:	Travis Coryea PE: 5892		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
45-1-5	Upholstery or padding is ripped, torn, or improperly repaired.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
69-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.