REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	4/30/2013	Time:	9:36 AM
Name of School Corporation:		OAK	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:			PO Box 550				
City:	Converse		Zip:	46919		County Number:	52
VIN:	4UZABRCS17CY1748	2		License Number:	4447	Bus Number:	21
Make of Body:	Thomas Built Buses, Inc.	Year:	2007	Make of Chassis:	Freightliner	Year:	2007
Bus Type:	С			Mileage:	Unknown		
Inspection Status: O		Inspected By:	Randy McPike		PE:	7018	

Violations - Rejected

Inspection Code	Description
25-1-2	Not fully charged
64-1-1	Lens is cracked, broken or discolored

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.