REPORT OF SCHOOL BUS INSPECTION

Type of 10:37 Annual Time: Date: 5/2/2013 Inspection: AM NORTH DAVIESS CO. COMM. SCHOOL Name of School Corporation: Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 4UZAAXBWX2CJ64882 B412D **Bus Number:** 15 Number: Make of Blue Bird Year: 2002 Freightliner Year: 2002 Make of Body: Corporation Chassis: **Bus Type:** С Mileage: Unknown Inspected PE: **Inspection Status:** R Travis Coryea 5892 By:

Violations - Rejected

Inspection Code	<u>Description</u>
22-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted).
45-1-3	Required padding is missing

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.