REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	5/2/2013	**Time:**	10:16 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL				**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58					
City:	Elnora	**Zip:**	47529		**County Number:**	14
VIN:	1HVBBAAP9XH204676		**License Number:**	B377D	**Bus Number:**	16
Make of Body:	Blue Bird Corporation	**Year:** 1999	**Make of Chassis:**	IC Corporation	**Year:**	1999
Bus Type:	C		**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Travis Coryea		**PE:**	5892

Violations - Rejected

Inspection Code	Description
43-1-1	Marker light or lens is missing, cracked, faded, wrong color, or inoperative.
45-1-3	Required padding is missing

Violations - Out of Service

Inspection Code	Description
33-2-2	Both lamps are inoperative on high beam.
69-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.