REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 5/2/2013 | Time: | 10:16 AM |
|---|--------------------------|-------|---------------------------|---------------------|-------------------|-------------------|-------------|
| Name of School Corporation: Address of School Corporation: | | | TH DAVIESS 5494 E SR 5 | Corp ID: | 141375 | | |
| City: | Elnora | | Zip: | 47529 | | County Number: | 14 |
| VIN: | 1HVBBAAP9XH2046 | 676 | | License Number: | B377D | Bus Number: | 16 |
| Make of Body: | Blue Bird Corporation | Year: | : 1999 | Make of Chassis: | IC Corporation | Year: | 1999 |
| Bus Type: | С | | | Mileage: | Unknown | | |
| Inspection Status: | 0 | | Inspected By: | Travis Coryea | | PE: | 5892 |

Violations - Rejected

| Inspection Code | Description | | | | | |
|-----------------|---|--|--|--|--|--|
| 43-1-1 | Marker light or lens is missing, cracked, faded, wrong color, or inoperative. | | | | | |
| 45-1-3 | Required padding is missing | | | | | |

Violations - Out of Service

| Inspection Code | Description |
|--------------------|---|
| 33-2-2 | Both lamps are inoperative on high beam. |
| 69-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.