

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/2/2013	<b>Time:</b> 9:13 AM
<b>Name of School Corporation:</b> NORTH DAVIESS CO. COMM. SCHOOL	<b>Corp ID:</b> 141375	
<b>Address of School Corporation:</b> 5494 E SR 58		
<b>City:</b> Elnora	<b>Zip:</b> 47529	<b>County Number:</b> 14
<b>VIN:</b> 1HVBRABP51A938144	<b>License Number:</b> B875H	<b>Bus Number:</b> 13
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2001	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2001	<b>Mileage:</b> Unknown	<b>Year:</b> 2001
<b>Bus Type:</b> C		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Travis Coryea	<b>PE:</b> 5892

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
40-1-4	There is debris in the bus. (needs cleaned) includes dirt
63-1-4	Front turn signal does not function properly
24-1-1	Mirror or mirror backs are loose or improperly mounted.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.